| •, | CLASSIFICATION SECRET | -1 |
|--|--|--|
| - | CENTRAL INTELLIGENCE AGENCY | DECENT NO. |
| | | REPORT NO |
| | INFORMATION REPORT | CD NO. 25X1 |
| OUNTRY | Poland | DATE DISTR. 18 August 1958 |
| UBJECT | Construction of New Basin in Hel Harbor, | NO. OF PAGES 2 |
| LACE CQUIRED | | NO. OF ENCLS. |
| ATE OF | 4 | SUPPLEMENT TO 25X1 . REPORT NO. |
| | DRC | CESSING COPY |
| of the united ST/ J. S. G., 31 AND 32. OF ITS CONTENTS H | ONTAINS INFORMATION AFFECTING THE MATIONAL DEFENSE ATTES WITHIN THE MEANING OF THE ESPICIACE ACT 50 ALS ARRENDED. ITS TRANSSITISION OR THE ESPECIATION BE ART MANNES TO AN SEASTMORIZED PERSON ESPERIODICION OF THIS FORM IS PROPIRITED. | |
| | In 1956, a new basin, about the size of the for Hele submarine harbor just had been constructed harbor. The two basins had only one entrence. | The concrete walls |
| | harbor. The two basins had only one entrance. I and breakwaters off the entrance of the new basiny the summer of 1956. The breakwater, which washove smooth water, will presumably be raised. basin was still under way in January 1957. The used until that date. A sketch of the installa | The concrete walls win had been completed an about 0.30 metars bredging work in the busin was net tion don the following pages. 25X1 not been confirmed asion of the Polish should should be to a page 1.50 |
| | harbor. The two basins had only one entrance. I and breakwaters off the entrance of the new base by the summer of 1956. The breakwater, which we above smooth water, will presumably be raised. basin was still under way in January 1957. The used until that date. A sketch of the installa is foun. Comment. The report which, so far, has sounds credible, since the project for the extended submarine harbor had already been mentions of the German Admiral Staff on Poland. The | The concrete walls sin had been completed an about 0.30 metars bredging work in the busin was net tion don't he following pages. 25X1 not been confirmed asion of the Polish shatch to a shatch to a confirmed factor of the 1939 Menual shatch to a confirmed confirmed asion of the 1939 Menual shatch to a confirmed confirmed asion of the 1939 Menual confirmed confirm |
| | harbor. The two basins had only one entrance. I and breakwaters off the entrance of the new base by the summer of 1956. The breakwater, which we above smooth water, will presumably be raised. basin was still under way in January 1957. The used until that date. A sketch of the installa is foun. Comment. The report which, so far, has sounds credible, since the project for the extended submarine harbor had already been mentions of the German Admiral Staff on Poland. The | The concrete walls sin had been completed an about 0.30 metars bredging work in the busin was net tion don't he following pages. 25X1 not been confirmed asion of the Polish shatch to a shatch to a confirmed factor of the 1939 Menual shatch to a confirmed confirmed asion of the 1939 Menual shatch to a confirmed confirmed asion of the 1939 Menual confirmed confirm |
| | harbor. The two basins had only one entrance. I and breakwaters off the entrance of the new base by the summer of 1956. The breakwater, which we above smooth water, will presumably be raised. basin was still under way in January 1957. The used until that date. A sketch of the installa is foun. Comment. The report which, so far, has sounds credible, since the project for the extended submarine harbor had already been mentions of the German Admiral Staff on Poland. The | The concrete walls sin had been completed an about 0.30 metars brodging work in the busin was not tion don the following pages. 25X1 not been confirmed asion of the Polish shatch to a shatch to a shatch to a confirmed factor of the 1939 Menual shatch to a confirmed confirmed asion of the 1939 Menual shatch to a confirmed c |
| STATE | harbor. The two basins had only one entrance. I and breakwaters off the entrance of the new base by the summer of 1956. The breakwater, which we above smooth water, will presumably be raised. basin was still under way in January 1957. The used until that date. A sketch of the installa is foun. Comment. The report which, so far, has sounds credible, since the project for the extended submarine harbor had already been mentions of the German Admiral Staff on Poland. The | The concrete walls sin had been completed an about 0.30 metars brodging work in the busin was net tion don the following pages. 25X1 not been confirmed asion of the Polish shatch to a shatch to a shatch to a confirmed factor. |

Sanitized Copy Approved for Release 2010/06/17: CIA-RDP80T00246A043700360001-7 SECRET U.S. OFFICIALS ONLY CLASSIFICATION COUNTRY Poland REPOST SUBJECT Improvement of Hela Harbor DATE OF PEPORT 9 July 1958 25X1 PLACE ACQUIRED LAST REFORT ON SUBJECT (If applicable) ANNUXES 1 sketch and legend on ditto

In 1956, a new basin, about the size of the former German, now Polish, Hela submarine herbor just had been constructed scutheast of the harbor. The two basins had only one entrance. The concrete walls and breakwaters off the entrance of the new basin had been completed by the summer of 1956. The breakwater, which was about 0.30 meters above smooth water, will presumably be raised. Dredging work in the basin was still under way in January 1957. The basin had not yet been used until that date.

25X1

Comment. The report which, so far, has not been confirmed sounds credible, since the project of the extension of the Polish Hela submarine harbor had already been mentioned in the 1939 Manual of the German Admiral Staff on Poland, the attached sketch to a large extent agrees with the project in the Manual. For sketch, see Annex.

SECRET - U.S. OFFICIALS ONLY

|--|

25X1

... 2 .

Legend

- 1. Three-story brick building, about 45 x 10 meters, which originated from the German era, and housed OWR (coastal fairway protection) and flotilla headquarters. First floor: office; second floor: office of chief and OWR chief of staff; third floor: office and billets of staff personnel.
- 2. Three-story brick building, about 45 x 25 x 10 meters, originating from the German era and housing CWR supply office, kitchen, mess halls and clubs. First floor: office, kitchen, mess halls; second floor: officers! club; third floor: CWR billets for EM.
- 3. New brick building housing gymnasium
- 4. Temporary building housing kitchen, mess halls, Ed canteen.
- Old, two-story brick building, about 20 x 8 meters, housing dispensary, billets for KM ammunition and fuel depot.
- 6. Single-story brick building housing ration supply depot
- 7. New temporary buildings with workshops
- 8. New brick building housing laundry.
- Fuel depot: fenced-in area with underground tank installations (mounds),
- 10. Ammunition dump: fenced-in area with sheds and bunkers covered by earth.
- 11. Filling station: fenced-in, little brick building with electrical pumps.
- 12. New concrete harbor wall
- 13. New breakwater
- 14. Embargo with position for sentry
- 15. Post headquarters
- 16. Temporary buildings housing billets for mavel guard unit

SECRET - U.S. OF FICIALS ONLY

SECRET - U.S. OFFICIALS ONLY

Acrex

25X1

.. 3 ...

- a. Landing place for speedboats S 51-55, 61-65 and torpedo outter
- b. Speedboat mother ship MOTAMA
- c. Landing place for mineaweepers
- d. Floating workshop
- s. Landing place for speedboats DS 41-44 and patrol boats
- f. Billets for special purposes in former minesweeper or engine (Hulk)
- g. Landing place for motor boats
- h. Landing place for minesusepers, scheduled for brets under construction,

SECRET - U.S. CFFICIALS CVLY

| 5 | Sanitized Copy Approved for Release 2010/06/17 : CIA-RDP8 | B0T00246A043700360001-7 |
|--------------------------------------|---|--|
| وحقن م | | and of the |
| | Classification secret | 25X |
| | CENTRAL INTELLIGENCE AGENCY | REPORT |
| | INFORMATION REPORT | CD NO. |
| UNTRY | Polend | DAME DIGHT |
| BJECT | Construction of New Basin | DATE DISTR. 18 August 1958 |
| POECI | in Hel Harbor | NO. OF PAGES 2 |
| ACE QUIRED | | NO. OF ENCLS. 25X |
| TE OF FO. | | SUPPLEMENT TO REPORT NO. |
| | | |
| i, c., 31 and 32. Its contents in | Myairs irponnation affecting the national defense are no manufacture within the names of the exponage act no as amended. Its transfession or the revelation is as amended. Its transfession or the revelation is an are handle to are enably defense in any hamble to are enably defense in the second of this point is promitted. | 25X1 |
| TEG BY CAN B | EPRODUCTION OF THIS FORM IS PROBLETED. | |
| | In 1966, a now had a short the site of the for | reer German, now Pollish. |
| | | i crutheast of the The concrete walls sin had been completed as about 0.30 meters Dradging work in the tesin was not stion 25X d on the following pages. |
| | Hela submarine harbor just had been constructed harbor. The two besins had only one entrance, and breakwaters off the entrance of the new being the summer of 1956. The breakwater, which we above smooth water, will presumably be raised, besin was still under way in January 1957. The used until that date. A sketch of the installs | i cratheast of the The concrete walls in had been completed as about 0.30 meters Dradging work in the besin was not tion d on the following pages. 25X not been confirmed nation of the Polish ad in the 1939 Manual aketch to a |
| , | Hela submarine harbor just had been constructed harbor. The two besins had only one entrance, and breakwaters off the entrance of the new barby the summer of 1955. The breakwater, which we above smooth water, will presumably be raised. besin was still under way in January 1957. The used until that date. A sketch of the installs is found that the country of the project for the extension of the German Admiral Staff on Poland. The | i cratheast of the The concrete walls in had been completed as about 0.30 meters Dradging work in the besin was not tion d on the following pages. 25X not been confirmed nation of the Polish ad in the 1939 Manual aketch to a |
| , | Hela submarine harbor just had been constructed harbor. The two besins had only one entrance, and breakwaters off the entrance of the new barby the summer of 1955. The breakwater, which we above smooth water, will presumably be raised. besin was still under way in January 1957. The used until that date. A sketch of the installs is found that the country of the project for the extension of the German Admiral Staff on Poland. The | i cratheast of the The concrete walls can had been completed as about 0.30 meters Dradging work in the tesin was not tion ad on the following pages. 25X not been confirmed neion of the Polish ed in the 1939 Manual sketch to a |
| , | Hela submarine harbor just had been constructed harbor. The two besins had only one entrance, and breakwaters off the entrance of the new barby the summer of 1955. The breakwater, which we above smooth water, will presumably be raised. besin was still under way in January 1957. The used until that date. A sketch of the installs is found that the country of the project for the extension of the German Admiral Staff on Poland. The | i cratheast of the The concrete walls can had been completed as about 0.30 meters Dradging work in the tesin was not tion ad on the following pages. 25X not been confirmed neion of the Polish ed in the 1939 Manual sketch to a |
| | Hela submarine harbor just had been constructed harbor. The two besins had only one entrance, and breakwaters off the entrance of the new barby the summer of 1955. The breakwater, which we above smooth water, will presumably be raised. besin was still under way in January 1957. The used until that date. A sketch of the installs is found that the country of the project for the extension of the German Admiral Staff on Poland. The | i cratheast of the The concrete walls can had been completed as about 0.30 meters Dradging work in the tesin was not tion ad on the following pages. 25X not been confirmed neion of the Polish ed in the 1939 Manual sketch to a |
| | Hela submarine harbor just had been constructed harbor. The two besins had only one entrance, and breakwaters off the entrance of the new barby the summer of 1955. The breakwater, which we above smooth water, will presumably be raised. besin was still under way in January 1957. The used until that date. A sketch of the installs is found that the country of the project for the extension of the German Admiral Staff on Poland. The | i cratheast of the The concrete walls can had been completed as about 0.30 meters Dradging work in the tesin was not tion ad on the following pages. 25X not been confirmed neion of the Polish ed in the 1939 Manual sketch to a |
| | Hela submarine harbor just had been constructed harbor. The two besins had only one entrance, and breakwaters off the entrance of the new barby the summer of 1955. The breakwater, which we above smooth water, will presumably be raised. besin was still under way in January 1957. The used until that date. A sketch of the installs is found that the country of the project for the extension of the German Admiral Staff on Poland. The | i cratheast of the The concrete walls can had been completed as about 0.30 meters Dradging work in the tesin was not tion ad on the following pages. 25X not been confirmed neion of the Polish ed in the 1939 Manual sketch to a |
| | Hela submarine harbor just had been constructed harbor. The two besins had only one entrance, and breakwaters off the entrance of the new barby the summer of 1955. The breakwater, which we above smooth water, will presumably be raised. besin was still under way in January 1957. The used until that date. A sketch of the installs is found that the country of the project for the extension of the German Admiral Staff on Poland. The | i cratheast of the The concrete walls can had been completed as about 0.30 meters Dradging work in the tesin was not tion ad on the following pages. 25X not been confirmed neion of the Polish ed in the 1939 Manual sketch to a |
| | Hela submarine harbor just had been constructed harbor. The two besins had only one entrance, and breakwaters off the entrance of the new barby the summer of 1955. The breakwater, which we above smooth water, will presumably be raised. besin was still under way in January 1957. The used until that date. A sketch of the installs is found that the country of the project for the extension of the German Admiral Staff on Poland. The | i cratheast of the The concrete walls can had been completed as about 0.30 meters Dradging work in the tesin was not tion ad on the following pages. 25X not been confirmed neion of the Polish ed in the 1939 Manual sketch to a |
| | Hela submarine harbor just had been constructed harbor. The two besins had only one entrance, and breakwaters off the entrance of the new barby the summer of 1955. The breakwater, which we above smooth water, will presumably be raised. besin was still under way in January 1957. The used until that date. A sketch of the installs is found that the country of the project for the extension of the German Admiral Staff on Poland. The | i cratheast of the The concrete walls can had been completed as about 0.30 meters Dradging work in the tesin was not tion ad on the following pages. 25X not been confirmed neion of the Polish ed in the 1939 Manual sketch to a |
| | Hela submarine harbor just had been constructed harbor. The two besins had only one entrance, and breakwaters off the entrance of the new barby the summer of 1955. The breakwater, which we above smooth water, will presumably be raised. besin was still under way in January 1957. The used until that date. A sketch of the installs is found that the country of the project for the extension of the German Admiral Staff on Poland. The | i cratheast of the The concrete walls can had been completed as about 0.30 meters Dradging work in the tesin was not tion ad on the following pages. 25X not been confirmed neion of the Polish ed in the 1939 Manual sketch to a |
| | Hela submarine harbor just had been constructed harbor. The two besins had only one entrance, and breakwaters off the entrance of the new barby the summer of 1955. The breakwater, which we above smooth water, will presumably be raised. besin was still under way in January 1957. The used until that date. A sketch of the installs is found that the country of the project for the extension of the German Admiral Staff on Poland. The | i cratheast of the The concrete walls can had been completed as about 0.30 meters Dradging work in the tesin was not tion ad on the following pages. 25X not been confirmed neion of the Polish ed in the 1939 Manual sketch to a |

STATE ARMY

| Annex | |
|--------------|--|
| - 2 - | |

25X1

Legand

- Three-stery brick building, about 45 x 10 meters, which originated from the German era, and housed OWR (coastal fairway protection) and flotilla headquarters. First floor: office; second floor: office of chief and OWR chief of staff; third floor: office and billets of staff personnel.
- 2. Three-story brick building, about 45 x 25 x 10 meters, originating from the German era and housing OWR supply office, kitchen, mess halls and clubs. First floor: office, kitchen, mess halls; second floor: officers' club; third floor: OWR billets for EM.
- 3. New brick hailding housing gyamasium
- 4. Nemporary building housing kitchen, mess halls, RM canteen.
- 5. Old, two-story brick building, about 20 x 8 meters, housing dispensery, killets for EM ammunition and fuel depot.
- 6. Single-story brick building housing ration supply depot
- 7. New temporary buildings with workshops
- 8. New brick building housing laundry.
- 9. Fuel depot: fonced-in area with underground tank installations (mounds).
- 10. Amminition dump: fenced-in area with sheds and bunkers covered by earth.
- 11. Filling station: fenced-in, little brick building with electrical pumps.
- 12. New concrete harbor well
- 13. New breakwater
- 14. Embargo with position for sentry
- 15. Post hasdquarters
- 16. Temporary buildings housing billets for neval guard unit

| Dalli W | | | |
|--------------|--|--|-------|
| Marketina as | | | 25X1 |
| | | | 20/(1 |
| | | | |

| SECRET - | • | |
|----------|---|-----|
| | 25 | 5X1 |
| Annex | | |
| | _ 3 _ | |

- a. Landing place for speedboats S 51-55, 61-65 and torpedo cutter
- b. Speedboat mother ship MOTAMA
- c. Landing place for minesweepers
- d. Floating workshop
- e. Landing place for speedboats DS 41-44 and patrol boats
- f. Billots for special purposes in former minesweeper or engine (Hulk)
- go landing place for motor beats
- $\cdot h_o$ Lending place for minesweepere, scheduled for boats under construction,

| عَاسَمَ إِنَّ وَعَرَافِهِ وَعَالَ الْمُعَالِمُ وَعَالَمُ وَعَلَيْكُ وَعَالَمُ الْمُعْمِدُ وَالْمُعْمِ | ~ | |
|---|---|--|
| | | |

25X1

SECRET US OFFICIALS ONLY


Objektskizze

anlage

Marinebasis HELA

ohne Maßstab, nach angaben Qu.





RET